



Stepper Motor

AGDxxx / AGAxxx configuration with Open Loop Stepper Motor



Application Note



www.agito-akribis.com

Member of Akribis Systems group

Revision History

Version	Description	Date
1.0	Initial Release	11 Aug 2022
2.0	Add Close Loop configuration	19 Oct 2022

Contact Information

Manufacturer Agito Akribis Systems Ltd., Member of Akribis Systems Group
Address 6 Yad-Harutsim St., P.O.Box 7172, Kfar-Saba 4464103
Telephone +972-9-8909797
Website www.agito-akribis.com

Copyright Notice

©2022 Agito Akribis Systems Ltd.

All rights reserved. This work may not be edited in any form or by any means without written permission of Agito Akribis Systems Ltd.

Products Rights

AGDx, AGCx, AGMx, AGAx, AGLx, and AGLx are products designed by Agito Akribis Systems Ltd. in Israel. Sales of the products are licensed to Akribis Systems Pte Ltd. under intercompany license agreement.

Agito Akribis Systems Ltd. has full rights to distribute above products worldwide.

Disclaimer

This product documentation was accurate and reliable at the time of its release.

Agito Akribis Systems Ltd. reserves the right to change the specifications of the product described in this manual without notice at any time.

Trademarks

Agito PCSuite is a trademark of Agito Akribis Systems Ltd..

Warranty

This product is warranted to be free of defects in material and workmanship and conforms to the specifications listed in this manual, for a period of 12 months from the shipment date from factory.

Contents

1	Introduction	4
1.1	Background	4
1.2	Scope	4
2	Setup	5
2.1	Equipment and overview	5
2.2	Setup Pictures	6
2.3	Wiring	8
2.4	Configuration	9
2.5	Tunning	13
3	Motion	16

1 Introduction

1.1 Background

In some application, customers want to use Agito controller to control stepper motor.

Agito controllers have built-in features that allow the user to control stepper motor in open loop.

1.2 Scope

This application note seeks to introduce how to do configuration and tuning in PCSuite software, and finally realize the open-loop control of stepper motor with Agito controller.

In this application note, AGM800 + AGA155-CI-2A10 are used. Other Central-I and integrated controllers also support this function.

2 Setup

2.1 Equipment and overview

The typical setup topology is presented in the following figure:



Figure 1. Setup topology

The example setup includes:

1. AGA155-CI-2A10 Central-i remote power amplifiers.
2. AGM800 Central-i master controller.
3. 2-Phase Bipolar Stepper Motor, Orientalmotor PKP268D28A2.

2.2 Setup Pictures




Figure 2. Setup picture 1 (Open loop)




Figure 3. Setup picture 2 (Open loop)



Figure 4. Setup picture 3 (Open loop)

2.3 Wiring

AGA155: X7 – Motor Power

Function	Pin Name	Pin #	Remarks
Motor Phase A	Phase A, M1	1	Motor Power
Motor Phase B	Phase B, M2	2	Motor Power
Motor Phase C	Phase C, M3	3	Motor Power, NC for voice coils
PE	PE	4	Motor PE




Figure 5. Stepper Motor Connection

**Note – Wiring for other controllers**

This example uses Agito controller, AGA155 for the example. Wiring information for other controllers or encoder protocols can be found in their respective Product Manuals.

2.4 Configuration



In PCSuite, navigate to COFIG Tab

**Open loop configuration:**


Set Type: Stepper in open loop.

Set Poles to 50 (or other number based on motor datasheet. Motors with step of 1.8° are 50 poles (most typical number of poles in steppers)).

Set stepper current to rated current of stepper (according datasheet). In position current can be lower to save energy when motor is not moving (if hold position not needed).

Stepper resolution set to 10bits (1024 micro stepping), can set up to 16bits (65536 micro steps).

Resolution 10 bits means 51,200 counts in 1 rev (2^{10} bits * 50 poles = 51200).




The screenshot shows the 'Motor' configuration window. On the left sidebar, there are icons for 'MOT' (selected) and 'PTP'. The main area is titled 'Motor' and contains a 'Motor Parameters' section with a 'Show Setup Wizard' checkbox. The parameters are as follows:

Parameter	Value	Unit
Type	6 - Stepper in open loop	
Number of pole pairs	50	
Stepper currents: in-motion	1,400	mA
in-position	500	mA
Stepper resolution	10	bits

Figure 6. Screen capture of MOT configuration in open loop.

Close loop configuration:

Set Type: Stepper in close loop.



The screenshot shows the 'Motor' configuration window with the 'Type' set to '7 - Stepper in closed loop'. The parameters are as follows:

Parameter	Value	Unit
Type	7 - Stepper in closed loop	
Number of pole pairs	1	
Stepper currents: in-motion	1,400	mA
in-position	500	mA
Stepper resolution	10	bits

Figure 7. Screen capture of MOT configuration in close loop.

Set Poles to 1.

Stepper resolution set to 10bits.



Open loop configuration:

Not relevant, since we don't have feedback.

Close loop configuration:

Set the encoder type and resolution based on the encoder in use.

Please make sure the “Invert direction” is correct.

Feedbacks

Dual loop

Dual Loop mode: 0 - No dual loop ?

Main encoder Reading: 1,362 Sine/Cosine status: OK

Type: 4 - Analog Sine/Cosine ?

See configuration items below

Multiplier (counts per cycle): 6 - 1024

Maximum input frequency: 8 - 250.0 kHz (raw: 0x5702)

Hysteresis: 0 - 0.0000 degrees

Resolution: 2,101,248 counts / rotation (or pitch) ?

Modulus range: 0 user-units

Emulation divider: 0

User units' factor: 65,536 / 65536 counts/user-units

Sine/Cosine encoder config. ?

Invert direction: 0 - Ascending ? Note: EncDir is not used for Analog Sine/Cosine encoder

Figure 8. Screen capture of FDBK configuration in close loop.



Tick “Mask main encoder errors”, if work in open loop.


Do Not tick “Mask main encoder errors”, if work in close loop.

Set position limits to +/-10,000,000.


Set allowed velocity to 2,000,000. **Note:** stepper motors are slow, motor speed cannot reach more 200-300 RPM.

Set allowed acceleration to 50,00,000


Motor stuck: current set to motor peak current. We don't have feedback, so need disable motor stuck protection.


 POS


Favorite


 PTP

Recent

 POS

 FDBK

 MOT



Protections: Position and Velocity

Motion limitations

Position limits: Reverse: Forward: user-units

Velocity/Acceleration limitations

Maximal allowed velocity: user-units/sec

Maximal allowed acceleration (future feature) user-units/sec²

Maximal errors

Maximal allowed position error: user-units

Maximal allowed velocity error: user-units/sec

Maximal errors in Open Loop modes (Open Loop, Injection and Identification)

Maximal allowed open loop position error: user-units

Maximal allowed open loop velocity error: user-units/sec

Motor stuck

Minimal current to activate protection: mA

Maximal velocity to define stuck: user-units/sec

Maximal time allowed in stuck: msec

Mask protections

☒ Mask main encoder errors
☒ Mask auxiliary encoder errors (if exist)


Figure 9. Screen capture of POS configuration.

COFIG  /POW 


Set Continues limitation to motor rated current.

Set Peak limitation to motor peak current.




Rest setting are standard as other motors.



Favorite



Recent

Protections: Power and Current

Current limitations and protections

Current units ?

Continuous limitation:	<input type="text" value="1,400"/>	mA
Peak limitation:	<input type="text" value="2,800"/>	mA
Peak maximum time:	<input type="text" value="20"/>	msec
Maximal phase current:	<input type="text" value="2,900"/>	mA
Maximal allowed motor current:	<input type="text" value="2,900"/>	mA
Maximal allowed power unit temperature:	<input type="text" value="80"/>	°C
Motor temperature sensor (PT100):	<input type="checkbox"/> Connected	
Maximal allowed motor temperature:	<input type="text" value="150"/>	°C

Bus voltage protections

Minimal allowed bus voltage:	<input type="text" value="80,000"/>	mV
Maximal timed bus voltage:	<input type="text" value="342,000"/>	mV
Maximal time for over voltage:	<input type="text" value="0"/>	msec
Absolute maximal allowed bus voltage:	<input type="text" value="342,000"/>	mV

PWM limitations

PWM limitations:	<input type="text" value="89"/>	%
------------------	---------------------------------	---

Figure 10. Screen capture of POW configuration.

2.5 Tunning

In PCSuite, navigate to TUNE Tab



TUNE  /PHAS 

No need.

TUNE  /CURR 

Perform tuning on step response of CurrRef, Ia and Ib, the highest amplitude. Use Proportional and Integral gains.

Note: Inductance measurement is not available for steppers, please refer to data sheet of stepper motor and fill in the value in PCSuite.




Figure 11. Screen capture of Data Recording Setup.




Figure 12. Screen capture of Current Tuning.



Open loop tuning:

No need, we work in open loop.

Close loop tuning:

Adjust the Position gain, until the motion performance meets the requirement.

Accel. FFW, Vel. FFW, Velocity gain and Velocity integral will not affect the performance of stepper motor.

PIV Tuning	Pos Filters	Vel Filters	Scheduling	PTP	Step...
Refer to Sched. Tab	Scheduling: None				Motor On
Position:	1				Motor Off
Gain:	<input type="text" value="2,000"/>				<input type="checkbox"/> Use PID <input data-bbox="1337 757 1380 801" type="button" value="?"/>
Accel. FFW:	<input type="text" value="0"/>				Vel. track factor:
Vel. FFW:	<input type="text" value="0"/>				<input type="text" value="100"/> %
Velocity:					Vel. FFW filter:
PI, gain:	<input type="text" value="0"/>				<input type="text" value="10,000"/> Hz
PI, integral:	<input type="text" value="0"/>				
<input checked="" type="checkbox"/> Perform auto data recording					
<input checked="" type="checkbox"/> Use predefined data recording setting					
<input type="button" value="Apply Pos Command"/>		<input type="button" value="Apply Vel Command"/>		<input type="button" value="Disable Command"/>	

Figure 13. Screen capture of PIV Tunning.

3 Motion

In PCSuite, navigate to MOTION Tab



MOTION



/PTP



Speed up to 200 RPM (depend on motor

Current shall reflect the speed, best work at rated motor current.

Open loop motion:

POS (Actual position) is always 0 (we have no feedback)

POSREF (position reference) is available, use POSREF as feedback as well.




Figure 14. Screen capture of Motion (Open loop).

Close loop motion:

POS (Actual position) will follow POSREF (position reference).




Figure 15. Screen capture of Motion (Open loop).

